

Consulting Engineers • Civil • Structural • Geotechnical • Materials Testing • Soil Borings • Surveying

1409 EMIL STREET, P.O. BOX 9538, MADISON, WIS. 53715 • TCL (608) 257-4848

April 28, 1980 C 9078

Mr. Chuck Howard c/o Rockford Blacktop Construction Company 600 Boylston Street Loves Park, IL 61111

Re: Hydrogeologic Investigation Pagel Pit Landfill .

Dear Mr. Howard:

This letter and the accompanying drawings present the results of the hydrogeologic investigation in the vicinity of Pagel Pit Landfill. Recently, two private wells (Lyford and Baxter) located along Lindenwood Road have been shown to be contaminated. The purpose of this investigation was to determine whether the Pagel Pit Landfill is contributing to the degradation of water quality at these wells. The investigation included the collection and analytical analysis of water quality samples, a review of the historical water quality records of wells in the vicinity of the landfill, and the analysis of recently measured water levels.

The direction of groundwater movement beneath a source of contamination dictates the potential migration direction of the contaminant within a groundwater flow system. As the accompanying water table map (Drawing C 9078-Al) indicates, groundwater flow in the vicinity of the landfill is from east to west, with shallow groundwater probably discharging into Killbuck Creek. The Lyford and Baxter wells are upgradient, or upstream, from the landfill with Monitoring Wells PP4 and PP6 being alongside, or marginally downgradient from the landfill.

The results of the water quality analyses of samples obtained on March 7, 1980 are attached. The data indicates that the source of contamination is probably to the east of the Lyford and Baxter residences. The two on-site monitoring wells, PP4 and PP6, displayed the lowest concentrations of parameters analyzed for, whereas the Lyford and Baxter wells displayed the highest concentrations of these parameters. The

Blacktop House and Scale-House wells were between these two extremes. The attached isoconcentration map of conductivity measurements illustrates the trend of decreasing concentrations to the west. Total alkalinity, total hardness, and nitrate concentrations at the Lyford and Baxter homes are generally two times higher than at PP4 and FP6 and display the same areal trends as conductivity. Nitrate concentrations at the Blacktop House, Lyford house, and Baxter house wells exceed the Interim Drinking Water Standard of 10 mg/l established by the United States Environmental Protection Agency. A comparison of the historical water quality data for PP4 and IP6 (starting on 1972) and the recent data shows no significant change in water quality at those two wells since 1972.

An abandoned solvent storage site, located approximately 2000 feet east of Lindenwood Road, appears to be the likely source of contamination at the Lyford and Baxter wells. Resed on a visual inspection of the site area and reports by landfill personnel, various waste materials including many buried barrels, were dumped in an abandoned limestone quarry. The potential for leachings from the waste to migrate down to the water table and contaminate groundwater in a downgradient direction is high in what is presumed to be a fractured limestone environment.

In summary, the water level and water quality data indicate the Pagel Pit Landfill is not the source of contamination at the Lyford and Baxter wells. It cannot be shown that no groundwater impact has occurred at the landfill since no directly downgradient wells exist. Currently available information indicates the source of contamination of the wells in question may be the abandoned solvent storage site. Additional documentation would be necessary to conclusively show the abandoned solvent storage site is the source of this contamination or to document an alternate source. Due to the unknown nature of waste material disposed of at the suspect site, we unge caution in using the affected water supplies and recommend the homeowners be so notified.

If you have any questions or comments regarding the above information, please do not hesitate to contact us.

Respectfully submitted,

WARZYN ENGINEERING INC.

Steven G. Willmann

Project Hanager

Daniel R. Viste

Chief Hydrogeological Section

SGW/DRV/dmf

Encl: Water Table Map, C 9078-Al

Isoconcentration Map-Conductivity, 6 9078 A2 Analytical Laboratory Results, Harch 7, 1980





ANALYTICAL LABORATORY RESULTS

Project Rockford Blacktop

Location Rockford, Illinois


Project No: C 9078
Sheet of App'd=1.
Date Issued: 2/3/80

→1409 EMIL STREET + P.O. BOX 9538, MADISON, WIS, 53²¹⁵ + TEL. (608) 257**-4848**

<u>Lample No.</u>	oH <u>Units</u>	Canductivity umnos/cm	* Total Alkalinity	Chemical Qxygen Demand	<u>Chloride</u>	Total Hardness	Nitrate Nitrogen	<u>Sulfate</u>
Saxter Well	6.55	1490	708	12	26	900	13	72
Blacktob House	5.80	360	426	<10	25	540	11	47
Lyford Weil	6.75	1310	464	21	50	670	28	65
Scale House & MP1	7.10	745	348	<10	12	420	4	32
Fagel Pit #PP4	7.30	655	280	12	21	330	4	18
Pagel Pit #PP5	7.40	. 640	252	<10	12	350	7	43


All parameters are mg/l unless otherwise stated.

^{*} Test run 3 days after sample collection



703.61 FF4 705.64 FP6	
714. 49' #1 EAKTER 714. 83' #2 LIFORD 702. 20' KC - KILLE	uck creer







SCALE: I'E IDOO'

MARCH MARCH STARTS

WARZYN




WATER TABLE MAP 3-20-80

Pagel Pit Landfill Rockford Blacktop Construction Company Winnebago County, Illinois

DAN ILIT

CHK DI YALI

APPO Downe En fiele last 4.28.80



conduction?	wient.
655	CPA
640	1284,
1490	MI PAXIER
1310	#2 Literio
145	#3 (65) (m) busis
୩ ୫೧	⁴ यं विजयन्त्रभूति संत्रिक्तः

LEGEND

LANDFILL AREA VIELL LOCAFION

-(900) - THE UF EQUAL CONSUCTIVITY EUCKENTENTICAL



GEALE: 1" × 1000"

*COMPRESENT WASTER GOINGS OF





ISOCONCENTRATION MAP-CONDUCTIVITY

Pagel Pit Landfill Rockford Blacktop Construction Company Winnebago County, Illinois

DAN TOLL CHE

Crox o DVSA

100 Daniel R. Ville

11411 4-28 80

C3018 AZ